

Response Marine, Inc.
 Stock for Norvelle 2695 Explorer w/ 8' house
 File: RMIDes\Norvelle\2695 Explorer....\Revised 081110\

Revised: 11/12/08
 Print Date: 8/20/19

Stock to Cutter:

<u>QTY</u>	<u>Thick</u>	<u>Width</u>	<u>Lnqth</u>	<u>lbs/ft^2</u>	<u>lbs</u>	
3/16" Sheet- 5086, Marine ASTM B-928						
1		0.190	60	120	2.67	134
3		0.190	48	240	2.67	641
8		0.190	60	240	2.67	2,136
2		0.190	72	240	2.67	641
2		0.190	60	336	2.67	748
16					Sub Total	4,299
1/4" Plate- 5086, Marine, ASTM B-928						
2		0.250	72	331	3.456	1,144
1		0.250	48	240	3.456	276
3					Sub Total	1,420
19					TOTAL	5,719

There should be no additional plate needed for the hull or cabin except as necessary for interior joinerwork.
 Extrusion will be needed for trim, caps, caps, coamings, etc.